

Russell A. Smith Plant Manager August 24, 2011

WO 11-0065

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

Subject:

Docket No. 50-482: Licensee Event Report 2011-007-00, "Manual

Reactor Trip due to Failed Controller Cards in the 'B' Feedwater Pump

Turbine Control System"

Gentlemen:

The enclosed Licensee Event Report is being submitted pursuant to 10 CFR 50.73(a)(2)(iv)(A) regarding a Reactor Trip and an Engineered Safety Features Actuation at the Wolf Creek Generating Station.

This letter contains no commitments. If you have any questions concerning this matter, please contact me at (620) 364-4156, or Mr. Gautam Sen at (620) 364-4175.

Sincerely,

Russell A. Smith

Enclosure

cc: E. E. Collins (NRC), w/e

J. R. Hall (NRC), w/e

G. B. Miller (NRC), w/e

Senior Resident Inspector (NRC), w/e

JE22

NRC FO	RM 36	6	U.S. NU	AR REGUI	_ATOR	Y COMM	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 10/31/2013									
U.S. NUCLEAR REGULATORY COMMISSION (10-2010) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1. FACILITY NAME WOLF CREEK GENERATING STATION							2. DOCKET NUMBER 05000 482			3. PAC	3. PAGE 1 OF 3					
4. TITLE Man		eactor	Trip due	to F	Failed Co	ontroll	er Card	s in the	·'Β' Feε	edwater	Pump T	urbine	Con	trol Sy	stem	
5. E\	/ENT D	ATE	6. L	ER I	NUMBER		7. REPORT DA		TE 8. OTHE		8. OTHER	FACILIT	TIES IN	IVOLVEI		
MONTH	DAY	YEAR	YEAR		QUENTIAL IUMBER	REV NO.	MONTH	DAY	YEAR FACILITY NAME			1	DOCKET NUMBER 05000			
06	26	2011	2011	- (007 -	00	08	24	2011	FACILITY N	AME		- 11	- 1	DOCKET NUMBER 05000	
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)											apply)					
Mode 1			20.220° 20.220° 20.220° 20.220° 20.220°	1(d) 3(a)(1 3(a)(2	2)(i)		☐ 20.2203(a)(3)(i) ☐ 20.2203(a)(3)(ii) ☐ 20.2203(a)(4) ☐ 50.36(c)(1)(i)(A) ☐ 50.36(c)(1)(ii)(A)			☐ 50.73(a)(2)(i)(C) ☐ 50.73(a)(2)(ii)(A) ☐ 50.73(a)(2)(ii)(B) ☐ 50.73(a)(2)(iii) ☑ 50.73(a)(2)(iv)(A)			☐ 50.73(a)(2)(vii) ☐ 50.73(a)(2)(viii)(A) ☐ 50.73(a)(2)(viii)(B) ☐ 50.73(a)(2)(ix)(A) ☐ 50.73(a)(2)(x)			
10. POWER LEVEL		20.2203 20.2203 20.2203 20.2203	3(a)(2 3(a)(2 3(a)(2	2)(iii) 2)(iv) 2)(v) 2)(vi)		50.36(c)(2) 50.46(a)(3)(ii) 50.73(a)(2)(i)(A) 50.73(a)(2)(i)(B)			☐ 50.73(a)(2)(v)(A) ☐ 50.73(a)(2)(v)(B) ☐ 50.73(a)(2)(v)(C) ☐ 50.73(a)(2)(v)(D)			☐ 73.71(a)(4) ☐ 73.71(a)(5) ☐ OTHER Specify in Abstract below or in NRC Form 366A				
					1	2. LICE	ENSEE CO	NTACT F	OR THIS	LER						
FACILITY N Gauta		en, Man	nager Re	gula	atory Affa	airs			TELEPHONE NUMBER (Include Area (Area Code)	
			13. COMPL	ETE (ONE LINE I	FOR E/	ACH COM	PONENT	FAILURE	DESCRIB	ED IN THIS	REPOR	T			
CAUSE		SYSTEM	COMPONEN	11 1	MANU- FACTURER		PORTABLE TO EPIX	C	AUSE	SYSTEM COMPONE			MANU- FACTURER		REPORTABLE TO EPIX	
х		SJ	Р		G080	Y							·			
		14.	SUPPLEM	ENTA	AL REPORT	EXPE	CTED				KPECTED	МО	NTH	DAY	YEAR	
☐ YES (If yes, complete 15. EXPECTED SU				SUBMISSION DATE)				NO SUBMISSION DATE				,				
ABSTRA	CT (Lin	nit to 1400	spaces, i.e.	., арр	proximately	15 sing	le-spaced	typewritte	n lines)							
	reactoper Systecaus turbit The	tor start ators m em and se of the ne cont safety s	tup when nanually t I the Eng trip was rol syste significan Updated	the tripp inee the m.	f Creek G e 'B' Mair ped the re ered Safe e failure o Two con of this ev fety Analy effects o	n Feed eactor ety Fe of one ntroller vent is lysis F	dwater pr. All controller All contro	oump trontrol ro actuation of two in the manual bection	ripped a ods fully n Syste o control nain turk ent is bo 15.2.7,	at 1609 (rinserte m perfo ller card bine cor bunded I "Loss o	CDT. Tr d and th ormed as ds in the ntrol syst by analys	ne confi e Read expect Main F em we	trol ro ctor T cted. Feedvere re repo	oom Trip The water eplaced	I.	

4 1 3

PLANT CONDITIONS AT THE TIME OF THE EVENT

Mode 1 82% power

DESCRIPTION OF THE EVENT

On June 26, 2011 the Wolf Creek Generating Station (WCGS) was in the process of power ascension at approximately 82 percent power, following Refueling Outage 18. The "B" Main Feedwater (MFW) pump [EIIS Code: SJ-P] unexpectedly tripped at 1609 CDT. The reactor was manually tripped with no complications. No structures, systems, or components were inoperable that contributed to the event.

Plant data showed that prior to the trip of the "B" Main Feedwater pump (MFP) the feed flow increased and the suction pressure for the MFP decreased. This rapid increase in generator feedwater flow rate and corresponding decrease in MFP suction pressure are an indirect indication that the MFP was accelerating in speed at the time of the trip. Extensive troubleshooting was conducted on the MFP, which identified an intermittent failure on one or both of two controller cards in the main feedwater turbine control system. The failure of the controller cards resulted in the turbine accelerating and tripping the MFP.

The reactor was manually tripped due to the loss of the "B" Main Feedwater pump, prior to an automatic trip occurring on low steam generator [EIIS Code: SG] levels. All control rods fully inserted and all safety equipment performed as designed. The Reactor Trip System (RTS) and the Engineered Safety Feature Actuation System (ESFAS) [EIIS Code: JE] performed as required. An Auxiliary Feedwater actuation signal occurred due to trip of both of the Main Feedwater pumps from a turbine trip and low SG levels. All auxiliary feedwater pumps started and operated as expected.

BASIS FOR REPORTABILITY

The reactor trip signal and actuation of the ESFAS instrumentation described in this event is reportable per 10 CFR 50.73(a)(2)(iv)(A), which requires reporting of "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section." Paragraph (B)(1) of 10 CFR 50.73(a)(2)(iv) includes "Reactor protection system (RPS) including: reactor scram or reactor trip." Paragraph (B)(6) of 10 CFR 50.73(a)(2)(iv) includes "PWR auxiliary or emergency feedwater."

ROOT CAUSE

The cause of the 'B' MFP trip was a failure of one or both of two controller cards in the main feedwater turbine control system.

NRC FORM 366A (10-2010) LICENSEE EVENT REPORT (LER)								
1. FACILITY NAME	2. DOCKET	6	3. PAGE					
WOLF CREEK GENERATING STATION	05000 482	YEAR 2011	SEQUENTIAL NUMBER	REV NO.	3	OF	3	

The controller cards are obsolete and no longer have vendor support. The equipment reliability program had targeted the controller cards for replacement. This original turbine control system is currently scheduled for replacement by a new MFP digital control system in Refueling Outage19 (Fall 2012).

CORRECTIVE ACTIONS

Two controller cards in the main feedwater turbine control system were replaced.

The main feedwater turbine control system, for both MFPs, is currently scheduled for replacement by a new MFP digital control system in Refueling Outage19 (Fall 2012).

SAFETY SIGNIFICANCE

The safety significance of this event is low. This event is analyzed as reported in WCGS Updated Safety Analysis Report (USAR) Section 15.2.7, "Loss of Normal Feedwater Flow." Results of the analysis show that a loss of normal feedwater does not adversely affect the core, the reactor coolant system, or the steam system, since the auxiliary feedwater capacity is such that reactor coolant water is not relieved from the pressurizer relief or safety valves.

There were no adverse effects on the health and safety of the public.

OPERATING EXPERIENCE/PREVIOUS SIMILAR OCCURRENCES

LER 2010-005-00 described a reactor trip due to a trip of a main feedwater pump caused by the failed transfer of an inverter to its alternate power supply.

LER 2010-006-00 described a reactor trip due to a trip of a main feedwater pump caused by a failed servo valve in the main feedwater speed control system.